



**VILENE, INTERLINING,
TAILOR'S HAMS and more...**

ZB pakje 5m



INFOSHEET

BLIND HEM TAPE

with	3 cm
Color	white or dark grey
Application	for easy and fast hemming: Finish the hem edge, iron in a hem (at least 4 cm), open the hem back up and insert hemtape. The thin side should be facing up, the visible blind stitch facing the hem and the invisible side facing outwards. With a damp cloth, iron on for around 10 seconds, section by section. You can remove a potential hem imprint by ironing underneath the upper hem edge with the tip of the iron.

Treatment in fine flexible fabrics



→ 5 to 6 times every spot



8 seconds



ORDER THIS INTERLINING IN OUR SHOP:

WWW.BEAUTYVOF.NL



WE ONLY SELL THE REAL VILENE...

Legend

	Wash up to 30 degrees		Iron without moisture
	Wash up to 40 degrees		Iron slowly with a sliding motion
	Wash up to 60 degrees		Ironing time
	Wash up to 95 degrees		Do not bleach
	Iron setting: Nylon / 1 dot		Can withstand cleaning with perchlooretheen, white spirit, R11 en R113
	Iron setting: Wool / 2 dots		Step by step ironing with pressure
	Iron setting: Cotton / 3 dots		Step by step ironing with low pressure
	Iron with pressure		Use steam when ironing
	Iron with low pressure		Sewable
	Iron with moisture		